

FIG.1




FIG.2




FIG.3




FIG.4




FIG.5a




FIG.5b




FIG.5c




FIG.6a




FIG.6b




FIG.7a




FIG.7b




FIG.8a




FIG.8b





FIG.9



2024-03-20 14:23:50

FIG.10a




FIG.10b




FIG. 11

1K






FIG.12a




FIG.12d




FIG.12b




FIG.12e




FIG.12c




FIG.13




FIG.14




FIG.15

NICKEL PLATING THICKNESS ( $\mu\text{m}$ )	CRACK OR THE LIKE OF NICKEL PLATING	STAINLESS-STEEL PLATE CURVE
3	×	○
5	△	○
8	○	○
17	○	○
20	○	○
25	○	×

FIG.16




FIG.17




FIG.18




FIG.19

